3/-45[illegible] Approved For Release 2002/06/17 : CIA-RDP78B04747A002100040009-6
DECLASS REVIEW by NIMA/DOD

STATINTL

[redacted]

We have found that the two eye pieces of the bi-ocular zoom part of the new STATINTL [redacted] do not have exactly the same magnification (about 10% different). This makes the eyes very tired after a short period of time. We do not see any means of easily adjusting this and would like to have something done to eliminate the problem STATINTL

STATINTL [redacted] STATINTL

1. Packed [redacted] 6 Mar 64 re above - talked to [redacted] who reworked the zoom for fit to the instrument. No reason why - Change eyepieces - 10x wide field. - w + without the shields. Be sure eyepiece is firmly in bore -

Replaced eyepieces with another pair. Seems to correct the problem. One 10x eyepiece marked 10x WF - the other marked 18x WF. This one has smaller field of view by about 10%, LAB STATINTL [redacted] said he thought the LAB type was in the Dynazoom - will check on it. [redacted] furnished two new eyepieces 3/23/64

STATINTL

Approved For Release 2002/06/17 : CIA-RDP78B04747A002100040009-6